## SPEC SHEET 1100M CNC MILLING MACHINE

## TORMACH.COM/1100M

## TORMACH®

| TRAVELS                              |  |  |  |
|--------------------------------------|--|--|--|
| X-Axis                               |  | 18" (457 mm)   |  |
| Y-Axis                               |  | 11" (279 mm)   |  |
| Z-Axis                               |  | 16.25" (413 mm)  |  |
| SPINDLE                              |  |  |  |
| Spindle Power                        |  | 2 hp (1.49 kW)   |  |
| Maximum Speed                        |  | 7500 RPM   |  |
| Transmission                         |  | Poly-V Belt  |  |
| Spindle Taper                        |  | R8   |  |
| Thread Machining                     |  | <ul><li>Tension/Compression</li><li>Auto-Reversing</li><li>Thread Mill</li></ul> |  |
| MAXIMUM FEED RATE                    |  |  |  |
| X- and Y-Axis                        |  | 110 IPM (2.79 m/min)   |  |
| Z-Axis                               |  | 90 IPM (2.29 m/min)  |  |
| POWER                                |  |  |  |
| Power Required                       |  | Single-Phase 230 Vac,<br>50/60 Hz, 20A breaker                                   |  |
| MACHINE SPECIFICATIONS               |  |  |  |
| Table Size                           |  | 34" × 9.5"<br>(863 mm × 241 mm)  |  |
| Table Slots                          |  | 5/8" (15.9 mm)<br>(three slots)  |  |
| Spindle Nose to Table Max Clearance  |  | 17" (432 mm)   |  |
| Spindle Centerline to Machine Column |  | 11" (279 mm)   |  |
| Typical System Footprint             |  | 69" × 56.5"<br>(1753 mm × 1435 mm)   |  |
| Overall System Height                |  | 92" (2337 mm)  |  |
| Typical System Weight                |  | 1600 lb (726 kg)   |  |
| FRAME                                |  |  |  |
| Frame and Table                      | Cast iron frame and table, with<br>hand-scraped hydrodynamic ways<br>and tapered adjustment gibs |  |  |
| Way Surfaces                         | Low-friction PTFE-filled,<br>Acetyl-bonded sliding surface.<br>Similar to Rulon® and Turcite®.   |  |  |



| ACCESSORIES                        |  |
|------------------------------------|--|
| Automatic Tool Changer             |  |
| Power Drawbar                      |  |
| 4th Axis                           |  |
| SmartCool™ Coolant System          |  |
| RapidTurn™ Chucker Lathe Accessory |  |
| Full Enclosure                     |  |
| High-Speed Spindle                 |  |

| CONTROLLER                                 |  |  |
|--|--|--|
|  | User-friendly design   |  |
| PathPilot® Controller<br>Standard Features | Support for up to 4-axis continuous machining                        |  |
|  | Intuitive conversational programming                                 |  |
|  | 80 GB of system program<br>memory                                    |  |
|  | Built-in Dropbox™<br>support for seamlessly<br>transferring programs |  |

**TORMACH**<sup>®</sup>